

SANITIZED

Authority: 1949 PA 300, Sec.257.622
Compliance: Required MSP UD-10E
Penalty: \$100 and/or 90 days (Rev 01/2016)

External # 1118335
Crash ID 2103865

Page 01 of 01
File Class 9300-1

STATE OF MICHIGAN TRAFFIC CRASH REPORT

Incident # 200030957

ORI MI 8121800
Department Name Ann Arbor Police Department

Reviewer CLOCK (31800)

Crash Date 09/17/2020
Crash Time 07:38
No. of Units 02
Crash Type Sideswipe-Same
Special Circumstances: None, Fleeing Police, Hit and Run, Unknown, School Bus, Animal
Special Checks: Fatal, Non-Traffic Area, ORV/Snowmobile

County 81 - Washtenaw
Traffic Control None
Relation to Roadway On the Road
Weather Cloudy
Area NON-FRWY Straight Roadway

City/Twsp 89 - Ann Arbor
Contributing Circumstances: 1st None, 2nd None
Light Dawn
Road Surface Condition Dry
Total Lanes 04
Speed Limit 45
Posted Yes

Work Zone (if applicable): Type, Workers Present, Activity, Location

Prefix N
Primary Road Name MAIN
Road Type ST
Suffix
Divided Roadway

Distance / Direction 10 Feet N
Trafficway Not Physically Divided

Prefix
Intersecting Road Name LAKESHORE
Road Type DR
Suffix
Divided Roadway

Unit Number 01
Unit Known Yes
State MI
Driver License Number #####
Date of Birth (Age) ###/###/#### (31)
License Type: Operator, Chauffeur, Moped
Endorsements: Cycle, Farm, Recreation
Sex M
Total Occupants 01
Hazardous Action Speed Too Fast

Unit Type MV
Driver Information: #####
ANN ARBOR, MI 48108 (###) ###-####
Driver is Owner Yes
Injury B
Position Front - Left
Restraint Helmet Worn

Driver Condition at Time of Crash: 1st Appeared Normal, 2nd
Driver Distracted By Not Distracted
Ejected Yes
Trapped
Airbag Deployed Not Equipped

Hospital UNIV OF MICHIGAN HEALTH SYSTEM
Ambulance HURON VALLEY AMBULANCE INC

Alcohol Suspected No
Contributing Factor No
Alcohol Test Type: Breath, Blood, Urine, Field, PBT, Refused, Not Offered
Alcohol Test Results: Pending, Test Results:
Interlock Device No

Drug Suspected No
Contributing Factor No
Drug Test Type: Blood, Urine, Field, Refused, Not Offered
Drug Test Results: Pending, Test Results:
Citation Issued: Hazardous, Other

Vehicle Registration QA953
State MI
Vehicle Description 2019 SUZUKI
Year 2019
Make SUZUKI
Model DL650
Color RED

VIN JS1C733B0K7101227
Vehicle Type Motorcycle
Special Vehicles Not Applicable
Private Trailer Type
Vehicle Defect

Automation System(s) in Vehicle No
Automation System Level in Vehicle No Automation
Automation System Level Engaged at Time of Crash No Automation

Insurance Company
Insurance Policy #
Towed By CORRIGAN TOWING DBA TRIANGLE
Towed To TRANGLE

Location of Greatest Damage 01
First Impact 01
Extent of Damage (Power Unit and/or Trailers) Disabling Damage
Vehicle Direction N
Vehicle Use Private
Action Prior Changing Lanes

Sequence of Events: First 17 - Motor Veh in Transport, Second 04 - Ran Off Roadway-Right, Third 32 - Other Post/Pole/Support, Fourth 13 - Individual Fell from Veh

Passenger Information: Date of Birth (Age), Sex, Position, Restraint, Injury, Ejected, Trapped, Airbag Deployed

Passenger Information: Date of Birth (Age), Sex, Position, Restraint, Injury, Ejected, Trapped, Airbag Deployed

Carrier Information: USDOT, MC, MPSC, Driver's CDL Type, Endorsements, CDL Exempt

GVWR/GCWR: 10,000 lbs. or Less, 10,001 - 26,000 lbs., Greater than 26,000 lbs.
Vehicle Configuration, Cargo Body Type, Medical Card, Hazardous Material, ID #, Class #

Owner Information: #####, ## ####-#### (###) ###-####

Damaged Property 08-TRAFFIC SIGN/POST
Public Yes
Owner & Phone: #####

